## Department of the Interior Airport Directory Landing Site Worksheet

Please provide the following information about the landing site you are requesting added to the DOI Airport Directory. Submit this request to your RAM/SAM for evaluation. Please include the following information:

## **Required information:**

Requesting Pilot's Name Ian Williams Date 06/17/2022

Agency, RAM/SAM Shad Sitz Duty Station Channel Islands

Site Name San Miguel Dry Lakebed Site Coordinates (DD MM.mm) 34° 02.60' N 120° 24.71'W

Elevation 389' Slope Level

Surface Condition Good Surface Type Dirt

Primary Landing Site Length 1468' Width 38' Orientation NW

Secondary Landing Site Length Width Orientation

Attended (Y/N) Yes No Maintained (Y/N) Yes No

Point of Contact for Site Conditions Ian Williams (805)658-5744 & David Mazurkiewicz (805)658-5774

Frequency of Use Periodic

PPE Recommendation and Justification No PPE except as required for overwater flight

Anticipated Seasonality of Use Year-round except following rains

Anticipated Inspection Frequency 30 days

Other Information

Island is owned by U.S. Navy and managed by NPS

Airstrip has a windsock and a fire extinguisher.

Prevailing wind is NW.

Fog can be persistent at this site.

On departure, avoid overflying sea lion rookery north of airstrip at Otter Harbor

Obstacle description (enter description of obstacle as it relates to the landing site and landing direction)

Approach Departure

1 2 3 4 5 6

1 Small hill to left of flight path 150' before

2

- 3 6 Small hill to left of flight path 1000' past end

4

5

## Surface Approach Departure



## Approach Departure

Approach Departure